

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: TN7503	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING _____		(X3) DATE SURVEY COMPLETED 09/26/2011
NAME OF PROVIDER OR SUPPLIER MAYFIELD REHABILITATION CENTER			STREET ADDRESS, CITY, STATE, ZIP CODE 200 MAYFIELD DRIVE SMYRNA, TN 37167		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE	
N 002	1200-8-6 No Deficiencies Based on observation on 9/26/11 at 6:00 PM, revealed no Fire Safety deficiencies.	N 002			

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Debbie Bowers

TITLE

Administrator

(X6) DATE

10/13/11

STATE FORM

6899

G8JU21

If continuation sheet 1 of 1

OCT 14 2011